

ALABAMA UNIFORM TRAFFIC ACCIDENT REPORT

DPS
Accident No

Shaded Areas To Be Used By Data Processing Only

Sheet 1 of 4 Sheet(s)

Microfilm No

Local Case No: **041205201**

LOCATION AND TIME	Date: 04 / 12 / 05 Month / Day / Year	Time: 12 : 30 AM / PM	Day of Week: M M / W / TH / F / S / B	County: 28	City: MENTONE	Rural / City	Highway Classification: I - Interstate <input checked="" type="radio"/> State <input checked="" type="radio"/> P - Private Prop. <input type="radio"/> F - Federal <input type="radio"/> C - County <input type="radio"/> O - Other <input type="radio"/>	M - Municipal P - Private Prop. O - Other	Local Zone		
	On Street Road or Highway: AL 117		At Intersection of or Between (Node 1): CR 631		And (Node 2): WEST RIVER RD.		01 - Overturned 02 - Fuel Explosion 03 - Immersion 04 - Gas Involves NON COLLISION EVENT 05 - Spin 06 - Road/Brake Collapse 07 - Jackknifed 08 - Pallet/Gargo Fell From Moving Vehicle 09 - Trailer Hitch Came Loose 10 - Other				
	Street or Road Code: S117		Mile Post: 7452		Node Code: 22		Foot From Node 1 or 2 (Circle One): 2		COLLISION EVENT 18 - Pedestrian 19 - Non-parked Vehicle 20 - Parked Vehicle 21 - Train 22 - Pedal Cycle 23 - Animal 24 - Object 25 - Crush Collision 26 - Utility Pole 27 - Non-breakaway Light 28 - Tree 29 - Fire Hydrant 30 - Pole or Column 31 - Non-breakaway Sign 32 - Gas Line 33 - Bridge 34 - Bridge Rail 35 - Cable Headrest 36 - Carving 37 - Retaining Wall 38 - Median Barrier 39 - Skewpile 40 - Grading 41 - Fence 42 - Boulder 43 - Arch 44 - Miscellaneous 45 - Gas Line 46 - Bridge 47 - Cable Headrest 48 - Carving 49 - Retaining Wall 50 - Median Barrier 51 - Skewpile 52 - Grading 53 - Fence 54 - Boulder 55 - Arch 56 - Overpass/Underpass 57 - Other Fixed Object 58 - Breakaway Sign 59 - Manhole 60 - Telephone Booth 61 - Guy Wire 62 - Breakaway Light 63 - Breakaway Object 64 - Bridge Abutment 65 - Animal with Rider 66 - Foreign Material in Road 67 - Pole 68 - Mine 69 - Other		
	Intersection Related: 1 Node 1 2 Node 2 <input checked="" type="radio"/> Not Int Related		Control Access: 1 Main Rd 2 Frontage Rd		3 Interchange 4 Entrance Ramp		5 Exit Ramp 6 N/A		Prime Contr Circum: 27		Prime Contr Code: 1

DRIVER	Unit No: 1	Driver Full Name: NICHALOS ALVIN THURMOND	Street Address: 1994 CR 358 PISGAH AL	City and State: AL	Zip: 35765	Telephone No: 256 657-6542			
	DOB: 06 / 13 / 80 Month / Day / Year	Race: W	Sex: M	DL State: AL	Driver License No: 6539119	DL Class: D C	DL Status: N	List Endorsements Not Completed With: NA	Residence Less Than 25 Miles: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	Place of Employment: JIMMY DUKE	Liability Insurance Co.: PROGRESSIVE	Social Security No: 4 2 4 - 2 1 - 8 3 9 2						
	Driver Condition: 1 - No Defect 2 - Apparently Asleep	3 - Fatigued 4 - Ill	8 - Other 9 - Unknown	Subriety: NA	Officer's Opinion: NA	Alcohol/Drugs: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Type Test Given: 1 - Blood Test 2 - Urine Test 3 - Breath Test 4 - Unable to Administer	5 - Refused Test	Test Results: NA
COM VEH	Maneuver: 01	Travel Road Name: AL117	Road Code: S117	Travel Direction: N	Other Contr Circumstance: 97	Prime Harm Event: 20	Event Loc: 1		
	Veh Year: 1992	Make: DODG	Model: 250	Body: OT	V.I.N.: 1B7KE26C4NS609403	License Tag Number: 25G951S	State: AL Year: 06		
	Owner's Name: JIMMY R DUKE	Street or R.F.D.: 16543 HWY 69	City: JAPPA	State: AL Zip: 35087					
	Type: 1 - Auto 2 - Sta. Wagon 3 - Pick Up 4 - Van 5 - Truck Tractor 6 - Other Truck 7 - Comm Bus 8 - School Bus 9 - Other Bus 10 - Motorcycle	11 - Moped 12 - M. Scooter 13 - Pedal Cycle 14 - Farm Mach. 15 - Train 16 - Road Equip. 17 - Ridden Animal 18 - M. Home (R.V.) 19 - ATV 20 - Other	1 - Personal 2 - Driver Trng 3 - Construction 4 - Ambulance/ Paramedical 5 - Military 6 - Taxi 7 - Transport Prop 8 - Agriculture 9 - Wrecker/Tow	10 - Police 11 - Other Business 12 - Bus/Pass. Transport. 13 - Fire Fighting 14 - Other	Hazardous Cargo: 1 - None 2 - Explosive 3 - Gas 4 - Flamm/Combust Liq. 5 - Flammable Solids 6 - Oxidizer/Peroxide 7 - Poison 8 - Radioactive Material 9 - Corrosive Material 10 - Other	Attachment: 1 - None 2 - Mobile Home 3 - Semi Trailer 4 - Utility Trailer 5 - Wheel Trailer 6 - Boat Trailer	7 - Camper Trailer 8 - Towed Vehicle 9 - Tanker 10 - Pole Trailer 11 - Double Trailer 12 - Other	Contributing Defect: 1 - Brakes 2 - Steering 3 - Power Plant 4 - Suspension 5 - Tires 6 - Exhaust 7 - Lights 8 - Turn Signal	9 - Windows/Windshield 10 - Restraint Sys. 11 - Wheels 12 - Truck Coupling 13 - Cargo 14 - Fuel System 15 - Other 16 - Unknown
Speed Limit: 45 MPH	Est. Speed: 40 MPH	Citation Offense Charged: NONE	Damage Severity: 1 - Non Visible 2 - Not Disabled	Vehicle Towed Away? Yes	Occupants in Use: 1	Enter Point of Initial Impact: 1			

DRIVER	Unit No: 2	Driver Full Name: DARRELL HOYT HOLDER	Street Address: 589 WARREN RD NE ROME GA	City and State: GA	Zip: 30165	Telephone No: 706 235-7011			
	DOB: 02 / 15 / 1953 Month / Day / Year	Race: W	Sex: M	DL State: GA	Driver License No: 260904965	DL Class: AM C	DL Status: C	List Endorsements Not Completed With: NA	Residence Less Than 25 Miles: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
	Place of Employment: COOSA STEEL CORP	Liability Insurance Co.: BROWN & BROWN	Social Security No: 2 6 0 - 9 0 - 4 9 6 5						
	Driver Condition: 1 - No Defect 2 - Apparently Asleep	3 - Fatigued 4 - Ill	8 - Other 9 - Unknown	Subriety: NA	Officer's Opinion: NA	Alcohol/Drugs: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Type Test Given: 1 - Blood Test 2 - Urine Test 3 - Breath Test 4 - Unable to Administer	5 - Refused Test	Test Results: NA
COM VEH	Maneuver: 01	Travel Road Name: AL117	Road Code: S117	Travel Direction: S	Other Contr Circumstance: 97	Prime Harm Event: 20	Event Loc: 1		
	Veh Year: 2000	Make: FRHT	Model: CC	Body: OT	V.I.N.: 1FUYSSB2YLB87721	License Tag Number: IP3093	State: GA Year: 05		
	Owner's Name: COOSA STEEL CORP.	Street or R.F.D.: 98 DARLINGTON DR SW	City: ROME	State: GA Zip: 30161					
	Type: 1 - Auto 2 - Sta. Wagon 3 - Pick Up 4 - Van 5 - Truck Tractor 6 - Other Truck 7 - Comm Bus 8 - School Bus 9 - Other Bus 10 - Motorcycle	11 - Moped 12 - M. Scooter 13 - Pedal Cycle 14 - Farm Mach. 15 - Train 16 - Road Equip. 17 - Ridden Animal 18 - M. Home (R.V.) 19 - ATV 20 - Other	1 - Personal 2 - Driver Trng 3 - Construction 4 - Ambulance/ Paramedical 5 - Military 6 - Taxi 7 - Transport Prop 8 - Agriculture 9 - Wrecker/Tow	10 - Police 11 - Other Business 12 - Bus/Pass. Transport. 13 - Fire Fighting 14 - Other	Hazardous Cargo: 1 - None 2 - Explosive 3 - Gas 4 - Flamm/Combust Liq. 5 - Flammable Solids 6 - Oxidizer/Peroxide 7 - Poison 8 - Radioactive Material 9 - Corrosive Material 10 - Other	Attachment: 1 - None 2 - Mobile Home 3 - Semi Trailer 4 - Utility Trailer 5 - Wheel Trailer 6 - Boat Trailer	7 - Camper Trailer 8 - Towed Vehicle 9 - Tanker 10 - Pole Trailer 11 - Double Trailer 12 - Other	Contributing Defect: 1 - Brakes 2 - Steering 3 - Power Plant 4 - Suspension 5 - Tires 6 - Exhaust 7 - Lights 8 - Turn Signal	9 - Windows/Windshield 10 - Restraint Sys. 11 - Wheels 12 - Truck Coupling 13 - Cargo 14 - Fuel System 15 - Other 16 - Unknown
Speed Limit: 45 MPH	Est. Speed: 40 MPH	Citation Offense Charged: NONE	Damage Severity: 1 - Non Visible 2 - Not Disabled	Vehicle Towed Away? Yes	Occupants in Use: 1	Enter Point of Initial Impact: 1			

CODES	Contributing Circumstances:	Driver Maneuver:	Pedestrian Action:	Event Location:
	01 - Improper Passing 02 - Improper Lane Change/Usage 03 - Improper Turn/U-Turn 04 - Following Too Close 05 - Misjudge Stopping Dist 06 - Over Speed Limit 07 - Avoid Object/Person/Veh 08 - Unseen Object/Person/Veh 09 - Improper Backing 10 - Inad Traffic Control 11 - Improper/No Signal 12 - Failure to Heed Sign/Sigal 13 - Improper Oving/Environ 14 - Road Defect 15 - Vision Obstruction 16 - Defective Equipment 17 - DUI 18 - Excess Min. Speed 19 - Improper Load/Size 20 - Improper Attachment 21 - Fail to Yield Right of Way 22 - Driver Condition 23 - Wrong Side of Road 24 - Veh Pushed/Towed by Veh 25 - Veh Pushed by Person 26 - Veh Left Road 27 - Driver Not in Control 28 - Load Shift 29 - Pallet/Cargo From Veh 30 - Ped Violation 31 - Veh Wagon Length 32 - Ped Under Influence 33 - Illegal/Improper Parking 34 - Hook 35 - Clear 36 - Unknown 01 - Go Straight Ahead 02 - Pass on Left 03 - Pass on 1-Way Street 04 - Pass on Right 05 - Go Straight-Left Turn Lane 06 - Go Straight-Right Turn Lane 07 - Change Lanes-Left 08 - Change Lanes-Right 09 - Merge-Left 10 - Merge-Right 11 - Wrong Side of Road 12 - Wrong Way-1 Way 13 - Right Turn 14 - Left Turn 15 - U-Turn 16 - Start From Park 17 - Start in Traffic 18 - Slowing/Stopping 19 - Stopped in Traffic 20 - Avoid Object in Road 21 - Entering Private Road/Property 22 - Ped/Cyc Rise w/ Traffic in Road 23 - Ped/Cyc Rise Against Traffic in Rd 01 - Ped/Cyc Rise Against Traffic in Rd 02 - Ped/Cyc Rise Across Road 03 - Ped/Cyc Rise in Bike Path 04 - Enter Parked Position 05 - Parked-Illegal 06 - Parked-Illegal 07 - Backing 08 - Pushed by Vehicle 09 - Pushed by Pedestrian 10 - Other 11 - Unknown 01 - Cross/Enter-Intersection 02 - Cross/Enter-Other 03 - Walk in Road-With Traffic 04 - Walk in Road-Against Traffic 05 - Stand in Roadway 06 - Get out of Vehicle 07 - Fugue/Work on Vehicle 08 - In Road-Other Veh's 09 - In Road-Paving 10 - In-Road Other 11 - Not in Road 12 - Other 13 - Unknown 1 - On Roadway 2 - Off Roadway 3 - Median 4 - Onway 5 - Private Road 6 - In Intersection			

General Instructions

Complete this form for each qualifying vehicle ONLY if the accident meets BOTH of the following criteria:

1. The accident involved a qualifying vehicle (truck with 6 or more tires or Haz/Mat placard, or a bus designed to carry 16 or more, including driver) and;
2. The accident resulted in at least one of the following: A. one or more fatalities B. one or more persons injured and taken from the scene for immediate medical attention, or C. one or more involved vehicles had to be towed from the scene as a result of disabling damage or had to receive assistance to leave.

Screening Information

Number of Qualifying Vehicles:

Number of Persons:

Trucks with 6 or more tires or Haz/Mat placard 1

Sustaining fatal injuries 0

Buses designed to carry 16 or more (including driver) 0

Transported for *immediate* medical treatment 1

Number of vehicles towed from scene due to damage or provided assistance 2

Vehicle Information

Gross Vehicle Weight Rating (GVWR)

Hazardous Material Involvement

A. Truck, tractor or bus 40000
B. Trailer or trailers (total) 40000
Total GVWR for unit (A+B) 80000

Did vehicle have a Haz/Mat placard Yes No

If Yes, include following information from placard

- A. Name or 4-digit number from diamond or box _____
B. The 1 -digit number from bottom of diamond _____

Was hazardous material released from THIS vehicle's cargo? Yes No

Total number of axles 5

Vehicle Configuration (circle one number)

1. Bus 2. Single unit truck (2 axles/ 6 or more tires) 3. Single unit truck (3 or more axles)
4. Truck with trailer 5. Truck tractor only (bobtail) 6. Tractor with semi-trailer 7. Tractor with double trailers
8. Tractor with triple trailers 9. Unknown class heavy truck 0. Any other 4-wheeled vehicle

Cargo Body Type (circle one number)

1. Bus 2. Van/enclosed box 3. Cargo tank 4. Flatbed 5. Dump
6. Concrete mixer 7. Auto transporter 8. Garbage/ refuse 9. Other _____

Motor Carrier Information

NOTE: IF NOT a motor carrier, enter NONE under Carrier Name, 0 for None under Carrier Identification Numbers, and go to Sequence Of Events Section

Carrier Name COOSA STEEL CORP.

Source (circle one number) 1. Vehicle side 2. Shipping papers 3. Driver 4. Other

Carrier mailing address (Street or P.O. Box) 98 DARLINGTON DR SW

City, State, Zip ROME GA 30161

Carrier Identification Numbers (40 None = 0)

US DOT 134073 ICC MC _____ STATE NO. _____ STATE _____

/ Sequence of Events

Note: for THIS vehicle - list up to four Event #1 15 Event #2 10 Event #3 _____ Event #4 _____

- | | | | | | |
|--------------------|----------------|------------------------|------------------------|--------------------------|------------------------|
| EVENT CODES | Non-Collision | 1. Ran off road | 2. Jackknife | 3. Overturned (rollover) | 4. Downhill runaway |
| | | 5. Cargo loss or shift | 6. Explosion or fire | 7. Separation of units | 8. Other non-collision |
| | Collision With | 9. Pedestrian | 10. Non-parked vehicle | 11. Parked vehicle | 12. Train |
| | | 13. Pedalcycle | 14. Animal | 15. Fixed object | 16. Other object |

Signature of Reporting Officer 	Officer ID <u>1402</u>	Reporting Police Agency ORJ <u>0280600</u>	Date <u>041205</u>	Time <u>1230</u>	AM PM <input checked="" type="radio"/> (M)
------------------------------------	---------------------------	---	-----------------------	---------------------	--

**ALABAMA
UNIFORM TRAFFIC ACCIDENT REPORT**

LOCAL CASE NO.

SHEET 3 OF 4 SHEET(S)

AST No. 34 Rev. 4/85

SUPPLEMENTAL SHEET

ADDITIONAL ACCIDENT VICTIMS

	Name	Address	Unit No.	Seat Pos.	Injury Type	Age	Sex	Ejection	First Aid By
3	_____	_____							
	Taken to	Taken by							
4	_____	_____							
	Taken to	Taken by							
5	_____	_____							
	Taken to	Taken by							
6	_____	_____							
	Taken to	Taken by							
7	_____	_____							
	Taken to	Taken by							
8	_____	_____							
	Taken to	Taken by							
9	_____	_____							
	Taken to	Taken by							
10	_____	_____							
	Taken to	Taken by							
11	_____	_____							
	Taken to	Taken by							
12	_____	_____							
	Taken to	Taken by							

ADDITIONAL NARRATIVE SPACE

DESCRIBE WHAT HAPPENED (Refer to vehicles by number)

VECH # 1 WAS GOING NORTH ON AL 117 APPROACHING SKYLINE BRIDGE ON WET ROADS FOLLOWING A TRACTOR TRAILOR AT APPROX. 40 MPH.

VECH # 2 WAS ON THE SKYLINE BRIDGE SOUTHBOUND AT APPROX 40 MPH. WHEN THE TRUCK VECH # 1 WAS FOLLOWING BRAKED HARD BECAUSE HE COULDN'T FIT ON SKYLINE BRIDGE WITH ANOTHER TRUCK, VECH # 1 PULLING A UT TRAILOR WAS UNABLE TO STOP AND LOST CONTROL OF HIS VECH ON WET ROADS AND CROSSED INTO THE PATH OF VECH # 2 COMING SOUTH ON AL 117. VECH # 2 RAN OFF THE RIGHT SIDE OF THE ROADWAY AND HIT A ROAD SIGN TRYING TO AVOID VECH # 1 BUT BECAUSE OF GUARD RAIL WAS UNABLE TO MOVE OVER ENOUGH TO AVOID VECH # 1 AND VECH #1 LF FENDER HIT VECH # 2 LF FENDER.

NOTE: THIS ACCIDENT WAS CAUSED BY THE NARROW BRIDGE ACROSS LITTLE RIVER ON AL 117. BRIDGE IS NOT WIDE ENOUGH FOR TWO TRACTOR TRAILORS TO MEET AT THE POSTED SPEED AND IN A CURVE IN WHICH THE BRIDGE SITS. VISION IS BLOCKED BY THE CURVE AND BY TREES ALONG THE SIDE OF THE ROADWAY ON THE NORTH BOUND APPROACH. IN THIS OFFICERS VIEW THIS ACCIDENT IS A RESULT OF THE DANGEROUS NARROW BRIDGE SET IN A CURVE WITH VISION OBSTRUCTED BY THE CURVE IN THE ROADWAY AND TREES LINING THE NORTH BOUND APPROACH TO THE BRIDGE. NORTH BOUND TRACTOR TRAILOR TRUCKS CAN'T CROSS THE BRIDGE WITHOUT CROSSING THE CENTER LINE OR THEIR TRAILORS WILL HIT THE END OF THE BRIDGE, THIS IS A DANGEROUS PROBLEM THAT HAS CAUSED SEVERAL ACCIDENTS AND NEEDS TO BE CORRECTED.

SEATING

Unit 1

1	2	3
24		
4	5	6
7	8	9

Other Involved Unit (Circle One)

10
11

12 - Pedestrian
13 - Rider of Domestic Animal
14 - Occ. of Non-Motorized Vehicle
15 - Victim of Other Circumstance/
Codes Not Applicable

Other Involved Safety Equipment

Unit 2

1	2	3
24		
4	5	6
7	8	9

Other Involved Unit (Circle One)

10
11

12 - Pedestrian
13 - Rider of Domestic Animal
14 - Occ. of Non-Motorized Vehicle
15 - Victim of Other Circumstance/
Codes Not Applicable

Other Involved Safety Equipment

- CODES**
- SAFETY EQUIPMENT**
- 01 - None Installed
 - 05 - Not Applicable
 - 08 - Unknown (Any Type)
 - Lap Belt Only**
 - 11 - Fastened
 - 12 - Not Fastened
 - Lap/Shoulder Harness**
 - 21 - Lap Only Used
 - 22 - Neither Used
 - 23 - Shoulder Only Used
 - 24 - Both Used
 - Motorcycle Helmet**
 - 31 - None Used
 - 32 - Used
 - Air Bags**
 - 41 - Deployed, Belts Used
 - 42 - Not Deployed, Belts Used
 - 43 - Deployed, Belts Not Used
 - 44 - Not Deployed, Belts Not Used
 - Child Restraint**
 - 61 - Child Restraint Used
 - 62 - Child Restraint Used
 - 63 - None Used
 - Foot Cycle/Pedestrian**
 - 91 - Contrasting Clothing
 - 92 - Non-contrasting Clothing

VICTIMS

N/A

Name	Address	Unit No	Seat Pos	Injury Type	Age	Sex	Ejection	First Aid By
NICHALOS ALVIN THURMOND	1994 CO RD 358 PISGAH AL 35765	1	1	A	24	M	N	A
Taken To		Taken By						
DCH		DAS						
Name		Address						
Taken To		Taken By						

CODES

Injury Type	Accused	First Aid By
K Killed B Bruise/Abrasion/Swelling	N - Not F - F-ly P - Probable	A - Ambulance Attended D - Doctor
A - Visible or Carried Non Scene C - Not Visible—Has Pain/Funk	T - Trapped U - Unknown A - Not Applicable	M - Paramedic O - Other
		P - Police U - Unknown N - None

NARRATIVE AND DIAGRAM

see page 4

Officer's Opinion of What Happened
SEE PAGE 3

ROADWAY ENVIRONMENT

For Each Roadway Environment Field, Circle One Entry for Each Involved Unit:

Unit	Contributing Road Defects	Surface Construction	Condition	Accident In Or Related To Road Construction Zone?	Material in Roadway (Contributing)	Material Source	Character
1	4 4 - None 1 1 - Shoulders Low	1 1 - Asphalt 2 2 - Concrete	1 1 - Dry 2 2 - Wet 3 3 - Icy	Yes No	1 1 - None 2 2 - Rocks 3 3 - Trees/Limbs 4 4 - Dirt	1 1 - Not Applicable 2 2 - Natural Environment 3 3 - Dropped From Vehicle 4 4 - Already in Road, But Not From Vehicle 8 8 - Other 9 9 - Unknown	1 1 - Straight—Level 2 2 - Straight—Down Grade 3 3 - Straight—Up Grade 4 4 - Straight—Hillcrest 5 5 - Curve—Level 6 6 - Curve—Down Grade 7 7 - Curve—Up Grade 8 8 - Curve—Hillcrest
2	2 2 - Shoulders High 3 3 - Holes, Bumps, Etc 8 8 - Other	3 3 - Brick 4 4 - Unpaved 8 8 - Other	4 4 - Snowy/Slushy 5 5 - Muddy 8 8 - Other	Yes No			

Vision Obscured By:	Traffic Control	Opposing Lanes Separated By:	Trafficway Lanes
97 97 - Not Obscured 1 1 - Buildings 2 2 - Signboards 3 3 - Trees, Crops, Bushes 4 4 - Blowing Snow/Sand 5 5 - Hillcrest 6 6 - Curve in Road 7 7 - Fog 8 8 - Parked Vehicle 9 9 - Moving Vehicle(s)	10 10 - Blinded by Sunlight 11 11 - Fire/Smoke 12 12 - Dust 13 13 - Blinded by Headlights 14 14 - Embankment 15 15 - Rain on Windshield 16 16 - Snow on Windshield 98 98 - Other 99 99 - Unknown	1 1 - Police Officer 2 2 - R.R. Crossing Gates 3 3 - R.R. Flashing Lights 4 4 - R.R. Cross Buck/Pave Mark 5 5 - Pedestrian Control 6 6 - Traffic Signal 7 7 - Flashing Beacon 8 8 - Stop Sign 9 9 - Yield Sign 10 10 - Lane Control Device	11 11 - Flagger 12 12 - No Passing Zone 97 97 - None 98 98 - Other
	Traffic Control Functioning: Yes/No DOT Railroad Crossing No	97 97 - None 1 1 - Paved Surface 2 2 - Unpaved Surface 3 3 - Broken Painted Line 4 4 - Solid Painted Line 5 5 - Concrete Barrier 6 6 - Metal Guard Rail 7 7 - Fence 8 8 - Other Barrier	1 1 - One Lane 2 2 - Two Lanes 3 3 - Three Lanes 4 4 - Four Lanes 5 5 - Five Lanes 6 6 - Six Lanes or More
		One-Way Street: Yes/No	

INVESTIGATION

Light	Weather	Locale	Non-Vehicular Property Damage	Property Damage Description
1 - Daylight 2 - Dawn 3 - Dusk 4 - Darkness—Road Not Lit 5 - Darkness—Road Lit	1 - Clear 2 - Cloudy 3 - Rain 4 - Snow 5 - Sleet/Hail 6 - Crosswind 7 - Fog 8 - Other	1 - Open Country 2 - Residential 3 - Shopping or Business 4 - Mfg or Industrial 5 - School 6 - Playground 8 - Other	1 - None Visible 2 - Light 3 - Moderate 4 - Severe	1 ROAD SIGN AND GRASS ALONG STATE RIGHTWAY
Time Police Notified AM/PM 12:35 PM	Time Police Arrived AM/PM 12:40 PM	Time EMS Arrived AM/PM 12:40 PM	Name of Photographer MICHAEL PUTMAN & JOHNNY FERGERSON	Description: ALABAMA DOT Address: MONTGOMERY AL
Witness Full Name MARGARITO RAMIREZ	Address 5059 BLUEGOOSE CT FLOWERY BRANCH GA 30542	Telephone 770 967-3114		
Name of Investigating Officer MICHAEL PUTMAN	Officer ID 1402	Agency ORI 0280600	Supervisor Reviewed	
Name of Other Investigating Officers at Scene JOHNNY FERGERSON	Officer ID 1401	Agency ORI 0280600		

AL 117



- A=15'
- B=32.6'
- C=22'
- D=53.6'
- E=123'
- F=24.9'
- G=50.8'

<p>Diagram Not to Scale</p> <p>Diagram Scale 1 inch = (10 feet) / (20 feet)</p>	<p>Location AL 117 & SKYLINE BRIDGE</p>	<p>Time 1230</p> <p>A.M. P.M. M.T.</p>
<p>Signature of Reporting Officer <i>[Signature]</i></p>	<p>Officer ID 1402</p>	<p>Reporting Police Agency ORI 0280600</p>
		<p>DATE</p> <p>Month 04 Day 12 Year 2005</p>

DN

- A=15'
- B=32.6'
- C=22'
- D=53.6'
- E=123'
- F=24.9'
- G=50.8'




Diagram Not to Scale Diagram Scale 1 inch = (10 feet) = (20 feet)	Location AL 117 & SKYLINE BRIDGE		Time 1230 AM PM MT	
	Officer ID 1402	Reporting Police Agency ORI 0280600	DATE Month: 04, Day: 12, Year: 2005	
Signature of Reporting Officer(s) 				

I WAS COMING FROM GEORGIA SOON I CROSS THE STATE LINE
ABOUT 5 MILES ON ALABAMA TOWN IS BRIDGE WITH CURV.
FIAT BAD TRUCK TRILER WAS COMING EAST. N I WAS COMING GOING
~~WAS~~ PICKUP TRUCK GAINING LOSS CONTROL. N THE DRIVEY
GOING EAST. HUB THE PICKUP TRUCK.

Margarito Ramirez (770) 967-3114

DRIVER LICENSE - NO.

GA 051619690 → 5059 BLUEGOOSE CT Flowerly Branch - 3054

COMPANY METAL USA

OAKWOOD GA. 335-88 7355